

www.costvsvalue.com





### Midrange Project Descriptions

### ATTIC INSULATION (FIBERGLASS)

Air-seal a 35x30 attic floor to address any air leakage from conditioned spaced to unconditioned space. Then add fiberglass loosefill insulation, placing it on top of existing insulation if present. Fiberglass loosefill is applied until thickness equating with R-30 insulation value is reached.

### **BACKUP POWER GENERATOR**

Install modular propane gas-powered electrical backup system with capacity for providing 70 amps of emergency power in two 240-volt circuits and six 120-volt circuits. Assume existing propane gas supply. Include generator mounted on 2-by-4-foot concrete or composite pad, automatic transfer switch, load center, exterior disconnect, and grounding rod. Include 30 feet of conduit and electrical cable for generator connections; grounded cable for circuits; 5 feet of flexible fuel line for connection to existing rigid gas supply line; and automotive-type storage battery.

### **BACKYARD PATIO**

Install a 20x20 flagstone patio on flat ground behind the home. Connect the house and patio by installing a lift-and-slide glass door on the back of the house. Place a gas-powered fire pit in the center of the patio and surround it with four mid-priced all-weather deck chairs. On the far end of the patio from the home, install a stone-veneer modular kitchen unit with gas grill, mini-refrigerator, sink, and storage. From each corner of the patio, erect a 20x20 cedar pergola capable of holding an awning that can shade the entire deck. Install mid-priced, low-voltage lights on the pergola sufficient to illuminate the patio at night. Install all needed gas and electrical connections underground from the home to the patio.

### **BASEMENT REMODEL**

Finish the lower level of a house to create a 20-by-30-foot entertaining area with wet bar and a 5-by-8-foot full bathroom; construct 24 linear feet of finished partition to enclose mechanical area. Walls and ceilings are painted drywall throughout; exterior walls are insulated; painted trim throughout. Include five sixpanel factory-painted hardboard doors with passage locksets. Electrical wiring to code.

Main room: Include 15 recessed ceiling light fixtures and three surface-mounted light fixtures, and a snap-together laminate flooring system.

Bathroom: Include standard white toilet, vanity with cultured marble top, resilient vinyl flooring, two-piece fiberglass shower unit, a light/fan combination, vanity light fixture, recessed medicine cabinet, towel and paper-holder hardware.

Bar area: Include 10 linear feet of raised-panel oak cabinets with laminate countertops, stainless steel bar sink, single-lever bar faucet, undercounter refrigerator, and vinyl floor tile.

### **BATHROOM ADDITION**

Add a full 6-by-8-foot bathroom over a crawlspace with poured concrete walls. Include cultured-marble vanity top with molded sink; standard chrome faucets; 30-by-60-inch white fiberglass tub/ shower with ceramic tile surround; single-lever temperature and pressure-balanced faucet; white low-profile toilet; general and spot lighting; electrical wiring to code; mirrored medicine cabinet; linen storage closet or cabinet; vinyl wallpaper; painted trim; and ceramic tile floor.

### **BATHROOM REMODEL**

Update an existing 5-by-7-foot bathroom. Replace all fixtures to include 30-by-60-inch porcelain-on-steel tub with 4-by-4-inch ceramic tile surround; new single-lever temperature and pressure-balanced shower control; standard white toilet; solid-surface vanity counter with integral sink; recessed medicine cabinet with light; ceramic tile floor; vinyl wallpaper.

### **DECK ADDITION (COMPOSITE)**

Add a 16-by-20-foot deck using pressure-treated joists supported by 4x4 posts anchored to concrete piers. Install composite deck material in a simple linear pattern. Include a built-in bench and planter of the same decking material. Include stairs, assuming three steps to grade. Provide a complete railing using a matching system made of the same composite as the decking material.

### **DECK ADDITION (WOOD)**

Add a 16-by-20-foot deck using pressure-treated joists supported by 4x4 posts anchored to concrete piers. Install pressure-treated deck boards in a simple linear pattern. Include a built-in bench and planter of the same decking material. Include stairs, assuming three steps to grade. Provide a complete railing system using pressure-treated wood posts, railings, and balusters.

### **ENTRY DOOR REPLACEMENT (FIBERGLASS)**

Remove existing 3-0/6-8 entry door and jambs and replace with fiberglass door with simulated wood grain, stained same color both sides; dual-pane, decorative half-glass panel with zinc caming; PVC-wrapped exterior trim in color to match existing trim; 2.5-inch interior colonial or ranch casings in hardwood stained to match door. Replace existing lockset with mortise lock with lever handle and integrated deadbolt.

### **ENTRY DOOR REPLACEMENT (STEEL)**

Remove existing 3-0/6-8 entry door and jambs and replace with new 20-gauge steel unit, including clear dual-pane half-glass panel, jambs, and aluminum threshold with composite stop. Door is factory finished with same color both sides. Exterior brick-mold and 2.5-inch interior colonial or ranch casings in poplar or equal prefinished to match door color. Replace existing lockset with new bored-lock.



### **FAMILY ROOM ADDITION**

In a style appropriate to the existing house, add a 16-by-25-foot room on a crawlspace foundation with siding and fiberglass shingle roof. Include drywall interior with fiberglass insulation, pre-finished hardwood floor, and 180 square feet of glazing including windows, atrium-style exterior doors, and two operable skylights. Tie into existing HVAC. Add electrical system to code, including 12 recessed ceiling lights.

### **GARAGE DOOR REPLACEMENT**

Remove and dispose of existing 16x7-foot garage door and tracks. Install new 4-section garage door on new galvanized steel tracks; reuse existing motorized opener. New door is uninsulated, single-layer, embossed steel with two coats of baked-on paint, galvanized steel hinges, and nylon rollers. 10-year limited warranty.

### **MAJOR KITCHEN REMODEL**

Update an outmoded 200-square-foot kitchen with a functional layout of 30 linear feet of semi-custom wood cabinets, including a 3-by-5-foot island; laminate countertops; and standard double-tub stainless-steel sink with standard single-lever faucet. Include energy-efficient range, ventilation system, built-in microwave, dishwasher, garbage disposal, and custom lighting. Add new resilient flooring. Finish with painted walls, trim, and ceiling.

### **MANUFACTURED STONE VENEER**

Remove a 300 square-foot continuous band of existing vinyl siding from the bottom third of the street-facing façade, beginning at the garage, continuing around the main entry, and ending at the corner of the side addition. Replace with adhered manufactured stone veneer, including 36 linear feet (LF) of sills, 40 LF of corners, and one address block. Installation includes two separate layers of water resistive barrier laid over bare sheathing, corrosion resistant lath and fasteners, and nominal ½-inch-thick mortar scratch coat and setting bed. Outline the archway using an 8x10-inch keystone and a soldier course of flats on either side.

### **MASTER SUITE ADDITION**

Add a 24-by-16-foot master bedroom suite over a crawlspace. Include walk-in closet/dressing area, a freestanding soaker tub, separate 3-by-4-foot ceramic tile shower, and double-bowl vanity with solid-surface countertop. Bedroom floor is carpet; bathroom floor is ceramic tile. Painted walls, ceiling, and trim. General and spot lighting, exhaust fan; electrical wiring to code.

### MINOR KITCHEN REMODEL

In a functional but dated 200-square-foot kitchen with 30 linear feet of cabinetry and countertops, leave cabinet boxes in place but replace fronts with new shaker-style wood panels and drawer fronts, including new hardware. Replace cooktop/oven range and slide-in refrigerator with new energy-efficient models. Replace

laminate countertops; install midpriced sink and faucet. Repaint trim, add wall covering, and remove and replace resilient flooring.

### **ROOFING REPLACEMENT**

Remove existing roofing to bare wood sheathing and dispose of properly. Install 30 squares of 235-pound fiberglass asphalt shingles (min. 25-year warranty) with new felt underlayment, galvanized drip edge, and mill-finish aluminum flashing. Assume a 5-square hip roof; custom flashing at two average-size skylights; and custom cap treatment at vented ridge.

### SIDING REPLACEMENT

Replace 1,250 square feet of existing siding with new siding. Include factory trim at all openings and corners.

### **TWO-STORY ADDITION**

In a style similar to the rest of the home, add a first-floor family room and a second-floor bedroom with full bathroom in a 24-by-16-foot two-story wing over a crawlspace. Add new HVAC system to handle addition; electrical wiring to code.

Family room: Include a prefabricated gas fireplace; 11 3-by-5-foot double-hung insulated clad-wood windows; an atrium-style exterior door; carpeted floors; painted drywall on walls and ceiling; and painted trim.

Bathroom: 5 by 8 feet. Include a one-piece fiberglass tub/shower unit; standard white toilet; wood vanity with solid-surface countertop; resilient vinyl flooring; and mirrored medicine cabinet with built-in light strip; papered walls; and painted trim; exhaust fan.

Bedroom: Include walk-in closet/dressing area; carpet; painted walls, ceiling, and trim; general and spot lighting.

### **UNIVERSAL DESIGN BATHROOM**

Begin with an existing 5x7 bathroom with toilet, tub shower, storage space, overhead light, tile floor, and single bathroom vanity with sink and a mirror behind the sink. Widen doorway so the room is accessible by wheelchair. Replace existing door with a wood interior door and standard interior door knobs with pushbutton lock. Reinforce bathroom walls as appropriate to support grab bars, towel hooks, and seats. Place electrical switches and outlets at heights that make them accessible to a person in a wheelchair. Replace existing 3x5 tub/shower unit with a walk-in, zero-threshold shower. Install a fold-down seat in the shower area. Use a height-adjustable/removable shower head. Replace existing toilet with comfort-height toilet. Install support bars as needed next to the toilet. Replace the bathroom vanity and sink with a unit whose doors are easily accessible while sitting and has space beneath for a person to sit comfortably at it. Install a standard porcelain sink and faucets with lever handles. Place mid-priced light fixtures on either side of the mirror. Replace overhead lighting with a 100-watt equivalent LED unit. Reconfigure storage so it can be accessed from a wheelchair.



### **Upscale Project Descriptions**

### **BATHROOM ADDITION**

Add a new 100-square-foot master bathroom to existing master bedroom over a crawlspace. Include 42-by-42-inch neo-angle shower with ceramic tile walls with accent strip, recessed shower caddy, body-spray fixtures, and frameless glass enclosure. Include a freestanding soaker tub with high-end faucets; stone countertop with two sinks; two mirrored medicine cabinets with lighting; a compartmentalized commode area with one-piece toilet; and a humidistat-controlled exhaust fan. Use all color fixtures. Use larger matching ceramic tiles on the floor, laid on the diagonal with ceramic tile base molding. Add general and spot lighting including waterproof shower fixture. Cabinetry shall include a custom drawer base and wall cabinets for a built-in look. Extend HVAC system, and include electric in-floor heating.

### **BATHROOM REMODEL**

Expand an existing 35-square-foot bathroom to 100 square feet within existing house footprint. Relocate all fixtures. Include 42-by-42-inch neo-angle shower with ceramic tile walls with accent strip, recessed shower caddy, body-spray fixtures, and frameless glass enclosure. Include a freestanding soaker tub with high-end faucets; stone countertop with two sinks; two mirrored medicine cabinets with lighting; a compartmentalized commode area with one-piece toilet; and a humidistat-controlled exhaust fan. Use all color fixtures. Use larger matching ceramic tiles on the floor, laid on the diagonal with ceramic tile base molding. Add general and spot lighting including waterproof shower fixture. Cabinetry shall include a custom drawer base and wall cabinets for a built-in look. Extend HVAC system, and include electric in-floor heating.

### **DECK ADDITION (COMPOSITE)**

Add a 16-by-20-foot deck using pressure-treated joists supported by 4x4 posts anchored to concrete piers. At one corner, add a second, 10-foot-diameter six-sided platform one step down from the main deck. Include stairs on the smaller deck, assuming three steps to grade. Install composite deck material in a simple linear pattern. Trim the perimeter joists and wrap the 4x4 posts with composite materials to match the decking. Using the same decking material, include a built-in bench and planter along one 16-foot side. On the remaining perimeter, provide a railing system using composite material of contrasting or complementary colors that includes decorative balusters, post caps, and lighting. Railing and trim should provide for overall curb appeal to the outdoor living space by integrating the deck with the home's color and architecture, creating a custom look.

### **GARAGE DOOR REPLACEMENT**

Remove and dispose of existing 16x7-foot garage door and tracks. Install new 4-section garage door on new heavy-duty galvanized steel tracks; reuse existing motorized opener. New door is high-tensilestrength steel with two coats of factory-applied paint, and foam insulated to minimum R-12, with thermal seals between pinch-resistant panels. Windows in top panel are ½-inch insulated

glass. Hardware includes galvanized steel hinges and ball-bearing urethane rollers. Lifetime warranty.

### **GRAND ENTRANCE (FIBERGLASS)**

Remove existing 3-0/6-8 entry door and cut and reframe opening for a 12-36-12 entrance door with dual sidelites. Move double-gang electrical box with two switches. Fiberglass door blank matches upscale entry, including color, threshold, lockset, and decorative half-glass; sidelites match door. PVC-wrapped exterior trim in color to match existing trim; wider interior colonial or ranch casings (3.5-inch to cover new jack studs) in hardwood stained to match door. All work to be completed in one day.

### **MAJOR KITCHEN REMODEL**

Update outmoded 200-square-foot kitchen with 30 linear feet of top-of-the-line custom white cabinets with built-in sliding shelves and other interior accessories. Include stone countertops with imported ceramic- or glass-tile backsplash; built-in refrigerator, commercial grade cooktop and vent hood, wall oven, and built-in microwave unit. Install high-end undermount sink with designer faucets and water filtration system. Add new general and task lighting, including low-voltage undercabinet lights. Install tile or similar flooring that looks like wood.

### **MASTER SUITE ADDITION**

Add a 32-by-20-foot master bedroom suite over a crawlspace.

Bedroom: Add a spacious sleeping area with lounging/sitting area adjacent to large master bathroom. Include custom bookcases and built-in storage with millwork details; high-end gas fireplace with stone hearth and custom mantle; and large walk-in closet/dressing area with natural light, mirrors, and linen storage. Add French doors to exterior.

Bathroom: Include a large walk-in shower with dual-shower system, stone shower walls and floor, and custom frameless glass enclosure. Add freestanding soaker tub. Include two sinks in separate custom vanities with stone countertops and large mirrors. Create partitioned area for luxury one-piece toilet.

General: Add 5-foot-long hospitality center with bar sink, undercounter refrigerator, custom cabinetry, granite or marble countertop, and microwave. Include soundproofing, in-floor heating, custom wall finishes and hardware, general and spot lighting, and lighting controls.

### WINDOW REPLACEMENT (VINYL)

Replace 10 existing 3-by-5-foot double-hung windows with insulated, low-E, simulated-divided-lite vinyl windows. Simulated wood-grain interior finish; custom-color exterior finish. Trim exterior to match existing; do not disturb existing interior trim.

### WINDOW REPLACEMENT (WOOD)

Replace 10 existing 3-by-5-foot double-hung windows with insulated, low-E, simulated-divided-lite wood windows. Interior finish of stained hardwood; exterior finish of custom-color aluminum cladding. Trim exterior to match existing; do not disturb existing interior trim.



### Reuse and Licensing of Data

### **COPYRIGHTED MATERIAL**

The Remodeling Cost vs. Value Report contains copyrighted material that is being made available in free downloadable PDF documents as a public service. Any reuse without express permission is prohibited, including but not limited to the following:

- 1. RESALE. The Cost vs. Value Report, whether in whole or part, may not be reproduced and sold in any format, including print, digital, electronic file, fax, or other medium.
- 2. PUBLICATION OF DATA. The Cost vs. Value Report, whether in whole or part, may not be distributed or published in any format, including print, digital, electronic file, fax, or other medium without obtaining express permission.
- 3. APPLICATIONS/SOFTWARE. The Cost vs. Value Report, whether in whole or part, may not be incorporated for use in any kind of computer- or Web-based application, calculator, database, or other automated, electronic, or digital device, instrument, or software except as licensed by Hanley Wood (see Licensing, below).

### **EXCERPTING COST VS. VALUE REPORT DATA**

Excerpts of Cost vs. Value Report data may not take the form of a chart or table that simulates the manner in which the data is displayed at www.costvsvalue.com.

Excerpts of Cost vs. Value Report data may, however, be made as part of a narrative, provided that the sum total of all excerpts from any publisher in all formats does not exceed data from more than five projects.

### **ACKNOWLEDGING COST VS. VALUE AS DATA SOURCE**

When excerpting Cost vs. Value Report data, refer to the "Remodeling 2016 Cost vs. Value Report" and include the URL www.costvsvalue.com, as in the following examples:

- "... according to the Remodeling 2017 Cost vs. Value Report (www.costvsvalue.com) ..."
- "... as compiled in the Remodeling 2017 Cost vs. Value Report

(www.costvsvalue.com) ...."

This form of citation should be used in the first instance on every page of a multipage online story that cites the Cost vs. Value Report on multiple pages. Subsequent references on a given page may be foreshortened to "Cost vs. Value Report."

All excerpts must be accompanied by one or more instances of the following acknowledgements of copyright:

"© 2017 Hanley Wood Media Inc. Complete data from the Remodeling

2017 Cost vs. Value Report can be downloaded free at www.costvsvalue.com."

### LICENSING OF 2017 COST VS. VALUE REPORT DATA

For permission to license data from the 2017 Cost vs. Value Report for use in any kind of computer- or Web-based application, calculator, database, or other automated, electronic, or digital device, instrument, or software, include the following in an email request to **costvsvaluepermissions@hanleywood.com** 

- a description of the application, calculator, or device for which use of the data is being requested. Include the length of time for which the license is sought.
- a detailed description of the material to be licensed (e.g., specific projects, cities, etc.).



PROJECT TYPE				
MIDRANGE	Job Cost	Resale Value	Cost Recouped	
Attic Insulation (fiberglass)	\$1,304	\$885	67.8%	
Backup Power Generator	12,165	4,676	38.4%	
Backyard Patio	49,360	28,455	57.6%	
Basement Remodel	66,079	49,000	74.2%	
Bathroom Addition	41,514	22,292	53.7%	
Bathroom Remodel	17,483	10,475	59.9%	
Deck Addition (composite)	16,896	8,877	52.5%	
Deck Addition (wood)	9,963	6,833	68.6%	
Entry Door Replacement (fiberglass)	3,240	1,989	61.4%	
Entry Door Replacement (steel)	1,378	1,691	122.7%	
Family Room Addition	84,527	52,682	62.3%	
Garage Door Replacement	1,681	1,605	95.5%	
Major Kitchen Remodel	60,037	38,565	64.2%	
Manufactured Stone Veneer	7,616	6,055	79.5%	
Master Suite Addition	114,682	72,500	63.2%	
Minor Kitchen Remodel	19,526	15,565	79.7%	
Roofing Replacement	20,267	12,211	60.2%	
Siding Replacement	13,611	9,658	71.0%	
Two-Story Addition	172,225	90,587	52.6%	
UPSCALE	Job Cost	Resale Value	Cost Recouped	
Universal Design Bathroom	\$ 14,408	\$ 9,705	67.4%	
Bathroom Addition	78,440	43,757	55.8%	
Bathroom Remodel	57,782	35,227	61.0%	
Deck Addition (composite)	38,173	19,921	52.2%	
Garage Door Replacement	3,244	2,810	86.6%	
Grand Entrance (fiberglass)	8,299	5,135	61.9%	
Major Kitchen Remodel	119,808	73,783	61.6%	
Master Suite Addition	242,409	131,400	54.2%	
Window Replacement (vinyl)	15,094	9,611	63.7%	
Window Replacement (wood)	18,314	9,806	53.5%	

This document contains copyrighted material and is not authorized for display on the Internet or for republication in any media for resale.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2017 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.



PROJECT TYPE	WES			
MIDRANGE	Job Cost	Resale Value	Cost Recouped	
Attic Insulation (fiberglass)	\$1,302	\$1,412	108.4%	
Backup Power Generator	12,269	6,685	54.5%	
Backyard Patio	48,167	29,217	60.7%	
Basement Remodel	64,827	52,368	80.8%	
Bathroom Addition	39,691	22,454	56.6%	
Bathroom Remodel	16,778	11,641	69.4%	
Deck Addition (composite)	16,408	10,190	62.1%	
Deck Addition (wood)	9,517	7,185	75.5%	
Entry Door Replacement (fiberglass)	3,221	2,427	75.3%	
Entry Door Replacement (steel)	1,349	1,020	75.6%	
Family Room Addition	81,306	63,577	78.2%	
Garage Door Replacement	1,629	1,113	68.4%	
Major Kitchen Remodel	58,884	41,234	70.0%	
Manufactured Stone Veneer	7,819	7,516	96.1%	
Master Suite Addition	111,262	76,706	68.9%	
Minor Kitchen Remodel	19,397	15,831	81.6%	
Roofing Replacement	19,125	13,234	69.2%	
Siding Replacement	13,514	9,501	70.3%	
Two-Story Addition	168,450	128,376	76.2%	
UPSCALE	Job Cost	Resale Value	Cost Recouped	
Universal Design Bathroom	\$ 14,049	\$ 9,746	69.4%	
Bathroom Addition	76,733	45,622	59.5%	
Bathroom Remodel	56,630	33,792	59.7%	
Deck Addition (composite)	37,008	20,987	56.7%	
Garage Door Replacement	3,263	2,740	84.0%	
Grand Entrance (fiberglass)	8,203	6,669	81.3%	
Major Kitchen Remodel	117,658	73,550	62.5%	
Master Suite Addition	238,472	143,109	60.0%	
Window Replacement (vinyl)	14,836	10,379	70.0%	
Window Replacement (wood)	18,132	12,703	70.1%	

CONFIDENCE LEVEL: 95% +/-10.1

This document contains copyrighted material and is not authorized for display on the Internet or for republication in any media for resale.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2017 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.




PROJECT TYPE	2017			
MIDRANGE	Job Cost	Resale Value	Cost Recouped	
Attic Insulation (fiberglass)	\$1,343	\$1,446	107.7%	
Backup Power Generator	12,860	6,940	54.0%	
Backyard Patio	51,985	28,546	54.9%	
Basement Remodel	71,115	49,768	70.0%	
Bathroom Addition	43,232	23,283	53.9%	
Bathroom Remodel	18,546	12,024	64.8%	
Deck Addition (composite)	17,249	11,252	65.2%	
Deck Addition (wood)	10,707	7,652	71.5%	
Entry Door Replacement (fiberglass)	3,276	2,550	77.8%	
Entry Door Replacement (steel)	1,413	1,282	90.7%	
Family Room Addition	89,566	62,055	69.3%	
Garage Door Replacement	1,749	1,345	76.9%	
Major Kitchen Remodel	62,158	40,560	65.3%	
Manufactured Stone Veneer	7,851	7,019	89.4%	
Master Suite Addition	119,533	77,506	64.8%	
Minor Kitchen Remodel	20,830	16,699	80.2%	
Roofing Replacement	20,664	14,214	68.8%	
Siding Replacement	14,518	11,093	76.4%	
Two-Story Addition	176,108	125,222	71.1%	
UPSCALE	Job Cost	Resale Value	Cost Recouped	
Universal Design Bathroom	\$ 15,730	\$ 10,766	68.4%	
Bathroom Addition	81,515	46,507	57.1%	
Bathroom Remodel	59,979	35,456	59.1%	
Deck Addition (composite)	39,339	22,171	56.4%	
Garage Door Replacement	3,304	2,810	85.0%	
Grand Entrance (fiberglass)	8,358	5,855	70.1%	
Major Kitchen Remodel	122,991	76,149	61.9%	
Master Suite Addition	250,687	150,140	59.9%	
Window Replacement (vinyl)	15,282	11,286	73.9%	
Window Replacement (wood)	18,759	13,691	73.0%	

CONFIDENCE LEVEL: 95% +/-2.6

Note: In four markets—Pensacola, Palm Springs, Quad Cities, and West Palm Beach—the job costs are an average of the costs for that project in that particular market's Census Division.

This document contains copyrighted material and is not authorized for display on the Internet or for republication in any media for resale.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2017 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.



Dallas, TX

hanley

MIDHANGE   Cost   Value   Recouped   Cost	PROJECT TYPE		DALLAS		WES	WEST SOUTH CENTRAL			2017 NATIONAL AVERAGES		
Backup Power Generator	MIDRANGE									Cost Recouped	
Backyard Patio	Attic Insulation (fiberglass)	\$1,304	\$885	67.8%	\$1,302	\$1,412	108.4%	\$1,343	\$1,446	107.7%	
Basement Remodel   66,079   49,000   74,2%   64,827   52,368   80,8%   71,115   49,768   70	Backup Power Generator	12,165	4,676	38.4%	12,269	6,685	54.5%	12,860	6,940	54.0%	
Bathroom Addition 41,514 22,292 53.7% 39,691 22,454 56.6% 43,232 23,283 53 Bathroom Remodel 17,483 10,475 59.9% 16,778 11,641 69.4% 18,546 12,024 64 Dex Addition (composite) 16,896 8,877 52.5% 16,408 10,190 62.1% 17,249 11,252 65 Deck Addition (wood) 9,963 6,833 68.6% 9,517 7,185 75.5% 10,707 7,652 71 Entry Door Replacement (fiberglass) 3,240 1,989 61.4% 3,221 2,427 75,3% 3,276 2,550 77 Entry Door Replacement (steel) 1,378 1,691 122.7% 1,349 1,020 75,6% 1,413 1,282 90 Family Room Addition 84,527 52,682 62.3% 81,306 63,577 78.2% 89,566 62,055 69 Garage Door Replacement 1,681 1,605 95,5% 1,629 1,113 68.4% 1,749 1,345 76 Major Kitchen Remodel 60,037 38,565 64.2% 58,884 41,234 70.0% 62,158 40,560 65 Manufactured Stone Veneer 7,616 6,055 79,5% 7,819 7,516 96,1% 7,851 7,019 89 Master Suite Addition 114,682 72,500 63,2% 111,262 76,706 68,9% 119,533 77,506 64 Minor Kitchen Remodel 19,526 15,565 79,7% 19,397 15,831 81,6% 20,830 16,699 80 Roofing Replacement 20,267 12,211 60,2% 19,125 13,234 69,2% 20,664 14,214 68 Siding Replacement 13,611 9,658 71,0% 13,514 9,501 70,3% 14,518 11,093 76 Two-Story Addition 78,440 8,9,705 67,4% \$14,049 \$9,746 69,4% \$15,730 \$10,766 68 Bathroom Addition 78,440 8,9,705 67,4% \$14,049 \$9,746 69,4% \$15,730 \$10,766 68 Bathroom Addition 78,440 8,9,705 67,4% \$14,049 \$9,746 69,4% \$15,730 \$10,766 68 Bathroom Remodel 57,782 35,227 61,0% 56,630 33,792 59,5% 59,99 35,466 59 Deck Addition (composite) 38,173 19,921 52,2% 37,008 20,987 56,7% 39,339 22,171 56 Garage Door Replacement 3,244 2,810 86,6% 3,263 2,740 84,0% 3,304 2,810 85 Grand Entrance (fiberglass) 8,299 5,135 61,9% 43,806 53,5% 418,132 12,703 70,0% 15,282 11,286 73 Window Replacement (wood) 18,314 9,806 53,5% 18,132 12,703 70,0% 15,282 11,286 73 Window Replacement (wood) 18,314 9,806 53,5% 18,132 12,703 70,0% 15,282 11,286 73	Backyard Patio	49,360	28,455	57.6%	48,167	29,217	60.7%	51,985	28,546	54.9%	
Bathroom Remodel   17,483   10,475   59.9%   16,778   11,641   69.4%   19,546   12,024   64	Basement Remodel	66,079	49,000	74.2%	64,827	52,368	80.8%	71,115	49,768	70.0%	
Deck Addition (composite)   16,896   8,877   52.5%   16,408   10,190   62.1%   17,249   11,252   65	Bathroom Addition	41,514	22,292	53.7%	39,691	22,454	56.6%	43,232	23,283	53.9%	
Deck Addition (wood)	Bathroom Remodel	17,483	10,475	59.9%	16,778	11,641	69.4%	18,546	12,024	64.8%	
Entry Door Replacement (fiberglass) 3,240 1,989 61.4% 3,221 2,427 75.3% 3,276 2,550 77 Entry Door Replacement (steel) 1,378 1,691 122.7% 1,349 1,020 75.6% 1,413 1,282 90 Family Room Addition 84,527 52,682 62.3% 81,306 63,577 78.2% 89,566 62,055 69 Garage Door Replacement 1,681 1,605 95.5% 1,629 1,113 68.4% 1,749 1,345 76 Major Kitchen Remodel 60,037 38,565 64.2% 58,884 41,234 70.0% 62,158 40,560 65 Manufactured Stone Veneer 7,616 6,055 79.5% 7,819 7,516 96.1% 7,851 7,019 89 Master Suite Addition 114,682 72,500 63.2% 111,262 76,706 68.9% 119,533 77,506 64 Minor Kitchen Remodel 19,526 15,565 79.7% 19,397 15,831 81,6% 20,830 16,699 80 Roofing Replacement 20,267 12,211 60.2% 19,125 13,234 69.2% 20,664 14,214 68 Siding Replacement 13,611 9,658 71.0% 13,514 9,501 70.3% 14,518 11,093 76 Two-Story Addition 172,225 90,587 52.6% 168,450 128,376 76.2% 176,108 125,222 71  UPSCALE Cost Value Recouped Cost Value Recouped Universal Design Bathroom \$14,408 \$9,705 67.4% \$14,049 \$9,746 69.4% \$15,730 \$10,766 68 Bathroom Addition 78,440 43,757 55.8% 76,733 45,622 59.5% 81,515 46,507 57 Bathroom Remodel 57,782 35,227 61.0% 56,630 33,792 59.7% 59,979 35,456 59 Deck Addition (composite) 38,173 19,921 52.2% 37,008 20,987 56.7% 39,339 22,171 56 Garage Door Replacement 3,244 2,810 86.6% 3,263 2,740 84.0% 3,304 2,810 85 Garage Door Replacement (iborglass) 8,299 5,135 61.9% 8,203 6,669 81.3% 8,358 5,855 70 Major Kitchen Remodel 119,808 73,783 61.6% 117,658 73,550 62.5% 122,991 76,149 61 Master Suite Addition 242,409 131,400 54.2% 238,472 143,109 60.0% 250,667 150,140 59 Window Replacement (wood) 18,314 9,806 53.5% 18,132 12,703 70.1% 18,759 13,691 73	Deck Addition (composite)	16,896	8,877	52.5%	16,408	10,190	62.1%	17,249	11,252	65.2%	
Entry Door Replacement (steel)	Deck Addition (wood)	9,963	6,833	68.6%	9,517	7,185	75.5%	10,707	7,652	71.5%	
Family Room Addition	Entry Door Replacement (fiberglass)	3,240	1,989	61.4%	3,221	2,427	75.3%	3,276	2,550	77.8%	
Garage Door Replacement         1,681         1,605         95.5%         1,629         1,113         68.4%         1,749         1,345         76           Major Kitchen Remodel         60,037         38,565         64.2%         58,884         41,234         70.0%         62,158         40,560         65           Manufactured Stone Veneer         7,616         6,055         79.5%         7,819         7,516         96.1%         7,851         7,019         89           Master Suite Addition         114,682         72,500         63.2%         111,262         76,706         68.9%         119,533         77,506         64           Minor Kitchen Remodel         19,526         15,565         79.7%         19,397         15,831         81.6%         20,830         16,699         80           Roofing Replacement         20,267         12,211         60.2%         19,125         13,234         69.2%         20,664         14,214         68           Siding Replacement         13,611         9,658         71.0%         13,514         9,501         70.3%         14,518         11,093         76           Two-Story Addition         172,225         90,587         52.6%         168,450         128,376 <th< td=""><td>Entry Door Replacement (steel)</td><td>1,378</td><td>1,691</td><td>122.7%</td><td>1,349</td><td>1,020</td><td>75.6%</td><td>1,413</td><td>1,282</td><td>90.7%</td></th<>	Entry Door Replacement (steel)	1,378	1,691	122.7%	1,349	1,020	75.6%	1,413	1,282	90.7%	
Major Kitchen Remodel         60,037         38,565         64.2%         58,884         41,234         70.0%         62,158         40,560         65           Manufactured Stone Veneer         7,616         6,055         79,5%         7,819         7,516         96.1%         7,851         7,019         89           Master Suite Addition         114,682         72,500         63.2%         111,262         76,706         68.9%         119,533         77,506         64           Minor Kitchen Remodel         19,526         15,565         79.7%         19,397         15,831         81.6%         20,830         16,699         80           Roofing Replacement         20,267         12,211         60.2%         19,125         13,234         69.2%         20,664         14,214         68           Siding Replacement         13,611         9,658         71.0%         13,514         9,501         70.3%         14,518         11,093         76           Two-Story Addition         172,225         90,587         52.6%         168,450         128,376         76.2%         176,108         125,222         71           UPSCALE         Job Resale Cost Value         Cost Value         Cost Value         Cost Recouped	Family Room Addition	84,527	52,682	62.3%	81,306	63,577	78.2%	89,566	62,055	69.3%	
Manufactured Stone Veneer         7,616         6,055         79.5%         7,819         7,516         96.1%         7,851         7,019         89           Master Suite Addition         114,682         72,500         63.2%         111,262         76,706         68.9%         119,533         77,506         64           Minor Kitchen Remodel         19,526         15,565         79.7%         19,397         15,831         81.6%         20,830         16,699         80           Roofing Replacement         20,267         12,211         60.2%         19,125         13,234         69.2%         20,664         14,214         68           Siding Replacement         13,611         9,658         71.0%         13,514         9,501         70.3%         14,518         11,093         76           Two-Story Addition         172,225         90,587         52.6%         168,450         128,376         76.2%         176,108         125,222         71           UPSCALE         Job Cost Value Recouped         Cost Val	Garage Door Replacement	1,681	1,605	95.5%	1,629	1,113	68.4%	1,749	1,345	76.9%	
Master Suite Addition         114,682         72,500         63.2%         111,262         76,706         68.9%         119,533         77,506         64           Minor Kitchen Remodel         19,526         15,565         79.7%         19,397         15,831         81.6%         20,830         16,699         80           Roofing Replacement         20,267         12,211         60.2%         19,125         13,234         69.2%         20,664         14,214         68           Siding Replacement         13,611         9,658         71.0%         13,514         9,501         70.3%         14,518         11,093         76           Two-Story Addition         172,225         90,587         52.6%         168,450         128,376         76.2%         176,108         125,222         71           UPSCALE         Job Cost Value         Resale Recouped         Cost Value         Cost Value         Recouped         Cost Value         Name Cost Recouped         Job Cost Value         Recouped         Cost Value         Recouped         Cost Value         Name Cost Recouped         S14,404         \$9,746         69,4%         \$15,730         \$10,766         68         88         81,515         46,507         57         84         84,602	Major Kitchen Remodel	60,037	38,565	64.2%	58,884	41,234	70.0%	62,158	40,560	65.3%	
Minor Kitchen Remodel         19,526         15,565         79.7%         19,397         15,831         81.6%         20,830         16,699         80           Roofing Replacement         20,267         12,211         60.2%         19,125         13,234         69.2%         20,664         14,214         68           Siding Replacement         13,611         9,658         71.0%         13,514         9,501         70.3%         14,518         11,093         76           Two-Story Addition         172,225         90,587         52.6%         168,450         128,376         76.2%         176,108         125,222         71           UPSCALE         Job Resale Cost Value Recouped         Cost Value Recouped<	Manufactured Stone Veneer	7,616	6,055	79.5%	7,819	7,516	96.1%	7,851	7,019	89.4%	
Roofing Replacement   20,267   12,211   60.2%   19,125   13,234   69.2%   20,664   14,214   68   Siding Replacement   13,611   9,658   71.0%   13,514   9,501   70.3%   14,518   11,093   76   Two-Story Addition   172,225   90,587   52.6%   168,450   128,376   76.2%   176,108   125,222   71      UPSCALE	Master Suite Addition	114,682	72,500	63.2%	111,262	76,706	68.9%	119,533	77,506	64.8%	
Siding Replacement   13,611   9,658   71.0%   13,514   9,501   70.3%   14,518   11,093   76	Minor Kitchen Remodel	19,526	15,565	79.7%	19,397	15,831	81.6%	20,830	16,699	80.2%	
UPSCALE         Job Cost         Resale Value         Cost Value         Job Cost         Resale Recouped         Cost Value         Job Cost Value         Resale Recouped         Cost Cost Value         Job Cost Value         Resale Recouped         Cost Value         Job Cost Value         Nature Value	Roofing Replacement	20,267	12,211	60.2%	19,125	13,234	69.2%	20,664	14,214	68.8%	
UPSCALE         Job Cost         Resale Value         Cost Value         Job Cost Value         Recouped Recouped         Cost Value         Job Cost Value         Resale Recouped Recouped         Cost Value         Job Cost Value         Resale Recouped Recouped         Cost Value         Value Recouped         Cost Value Part Value         Value Value Recouped         Cost Value Value Part Value         Value Value Value Value Part Value         Value	Siding Replacement	13,611	9,658	71.0%	13,514	9,501	70.3%	14,518	11,093	76.4%	
UPSCALE         Cost         Value         Recouped         Cost         Value         Recouped           Universal Design Bathroom         \$14,408         \$9,705         67.4%         \$14,049         \$9,746         69.4%         \$15,730         \$10,766         68           Bathroom Addition         78,440         43,757         55.8%         76,733         45,622         59.5%         81,515         46,507         57           Bathroom Remodel         57,782         35,227         61.0%         56,630         33,792         59.7%         59,979         35,456         59           Deck Addition (composite)         38,173         19,921         52.2%         37,008         20,987         56.7%         39,339         22,171         56           Garage Door Replacement         3,244         2,810         86.6%         3,263         2,740         84.0%         3,304         2,810         85           Grand Entrance (fiberglass)         8,299         5,135         61.9%         8,203         6,669         81.3%         8,358         5,855         70           Major Kitchen Remodel         119,808         73,783         61.6%         117,658         73,550         62.5%         122,991         76,149 <t< td=""><td>Two-Story Addition</td><td>172,225</td><td>90,587</td><td>52.6%</td><td>168,450</td><td>128,376</td><td>76.2%</td><td>176,108</td><td>125,222</td><td>71.1%</td></t<>	Two-Story Addition	172,225	90,587	52.6%	168,450	128,376	76.2%	176,108	125,222	71.1%	
Bathroom Addition         78,440         43,757         55.8%         76,733         45,622         59.5%         81,515         46,507         57           Bathroom Remodel         57,782         35,227         61.0%         56,630         33,792         59.7%         59,979         35,456         59           Deck Addition (composite)         38,173         19,921         52.2%         37,008         20,987         56.7%         39,339         22,171         56           Garage Door Replacement         3,244         2,810         86.6%         3,263         2,740         84.0%         3,304         2,810         85           Grand Entrance (fiberglass)         8,299         5,135         61.9%         8,203         6,669         81.3%         8,358         5,855         70           Major Kitchen Remodel         119,808         73,783         61.6%         117,658         73,550         62.5%         122,991         76,149         61           Master Suite Addition         242,409         131,400         54.2%         238,472         143,109         60.0%         250,687         150,140         59           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703 <th></th> <th>Cost</th> <th>Value</th> <th>Recouped</th> <th>Cost</th> <th>Value</th> <th>Recouped</th> <th>Cost</th> <th>Value</th> <th>Cost Recouped</th>		Cost	Value	Recouped	Cost	Value	Recouped	Cost	Value	Cost Recouped	
Bathroom Remodel         57,782         35,227         61.0%         56,630         33,792         59.7%         59,979         35,456         59           Deck Addition (composite)         38,173         19,921         52.2%         37,008         20,987         56.7%         39,339         22,171         56           Garage Door Replacement         3,244         2,810         86.6%         3,263         2,740         84.0%         3,304         2,810         85           Grand Entrance (fiberglass)         8,299         5,135         61.9%         8,203         6,669         81.3%         8,358         5,855         70           Major Kitchen Remodel         119,808         73,783         61.6%         117,658         73,550         62.5%         122,991         76,149         61           Master Suite Addition         242,409         131,400         54.2%         238,472         143,109         60.0%         250,687         150,140         59           Window Replacement (vinyl)         15,094         9,611         63.7%         14,836         10,379         70.0%         15,282         11,286         73           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12										68.4%	
Deck Addition (composite)         38,173         19,921         52.2%         37,008         20,987         56.7%         39,339         22,171         56           Garage Door Replacement         3,244         2,810         86.6%         3,263         2,740         84.0%         3,304         2,810         85           Grand Entrance (fiberglass)         8,299         5,135         61.9%         8,203         6,669         81.3%         8,358         5,855         70           Major Kitchen Remodel         119,808         73,783         61.6%         117,658         73,550         62.5%         122,991         76,149         61           Master Suite Addition         242,409         131,400         54.2%         238,472         143,109         60.0%         250,687         150,140         59           Window Replacement (vinyl)         15,094         9,611         63.7%         14,836         10,379         70.0%         15,282         11,286         73           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703         70.1%         18,759         13,691         73						•			·	57.1%	
Garage Door Replacement         3,244         2,810         86.6%         3,263         2,740         84.0%         3,304         2,810         85           Grand Entrance (fiberglass)         8,299         5,135         61.9%         8,203         6,669         81.3%         8,358         5,855         70           Major Kitchen Remodel         119,808         73,783         61.6%         117,658         73,550         62.5%         122,991         76,149         61           Master Suite Addition         242,409         131,400         54.2%         238,472         143,109         60.0%         250,687         150,140         59           Window Replacement (vinyl)         15,094         9,611         63.7%         14,836         10,379         70.0%         15,282         11,286         73           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703         70.1%         18,759         13,691         73		•								59.1%	
Grand Entrance (fiberglass)         8,299         5,135         61.9%         8,203         6,669         81.3%         8,358         5,855         70           Major Kitchen Remodel         119,808         73,783         61.6%         117,658         73,550         62.5%         122,991         76,149         61           Master Suite Addition         242,409         131,400         54.2%         238,472         143,109         60.0%         250,687         150,140         59           Window Replacement (vinyl)         15,094         9,611         63.7%         14,836         10,379         70.0%         15,282         11,286         73           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703         70.1%         18,759         13,691         73	· · · · · ·		<u>.</u>		·			,	,	56.4%	
Major Kitchen Remodel         119,808         73,783         61.6%         117,658         73,550         62.5%         122,991         76,149         61           Master Suite Addition         242,409         131,400         54.2%         238,472         143,109         60.0%         250,687         150,140         59           Window Replacement (vinyl)         15,094         9,611         63.7%         14,836         10,379         70.0%         15,282         11,286         73           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703         70.1%         18,759         13,691         73						, -		-,		85.0%	
Master Suite Addition         242,409         131,400         54.2%         238,472         143,109         60.0%         250,687         150,140         59           Window Replacement (vinyl)         15,094         9,611         63.7%         14,836         10,379         70.0%         15,282         11,286         73           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703         70.1%         18,759         13,691         73	<u> </u>				-					70.1%	
Window Replacement (vinyl)         15,094         9,611         63.7%         14,836         10,379         70.0%         15,282         11,286         73           Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703         70.1%         18,759         13,691         73		-,	-,			•				61.9%	
Window Replacement (wood)         18,314         9,806         53.5%         18,132         12,703         70.1%         18,759         13,691         73		•			· '			· · · · · · · · · · · · · · · · · · ·		59.9%	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		-,	-,-		,	- ,		-, -		73.9%	
CONFIDENCE LEVEL: 95% +/-10.1 CONFIDENCE LEVEL: 95% +/-2.6	Window Replacement (wood)	18,314	9,806	53.5%	18,132	12,703	70.1%	18,759	13,691	73.0%	
					CONFIDENCE	LEVEL: 95% +/-10	0.1	CONFIDENCE LE	EVEL: 95% +/-2.	6	

Note: In four markets—Pensacola, Palm Springs, Quad Cities, and West Palm Beach—the job costs are an average of the costs for that project in that particular market's Census Division.

©2017 Hanley Wood Media Inc. Republication or dissemination of Remodeling's 2016 Cost vs. Value Report is expressly prohibited without the written permission of Hanley Wood Media Inc. "Cost vs. Value" is a registered trademark of Hanley Wood Media Inc. Unauthorized use is prohibited.



The 2017 REMODELING Cost vs. Value Report has been brought to you thanks to the following companies.

















# The next generation of Outdoor Living products

Get more out of your deck with Clubhouse Decking. Clubhouse offers the natural, deep-grain look of real wood, while providing the superior strength of PVC. And its dual-color, dual embossed planks offer multiple design options, making it easy to find exactly what you're looking for. The next generation of decking is finally here. **clubhousedecking.com** 



CLUBHOUSEDECKING.COM



# Designed for Decks and the People Who Build Them.

# Simple is Beautiful.

It's simple—open the package, remove the panels, fasten the brackets. Because you already have enough in your life that's complicated.

Visit www.FortressRailing.com to learn more.



844.909.2999





## Introducing the New James Hardie Contractor Alliance™ Program

Align with the industry leader and we can help grow your presence in the community. Build on our unique marketing tools, lead generation support, and training on everything from in-home sales to installation. Strengthen your business with the #1 brand of siding to stand out from the competition. The more you connect with us, the deeper our commitment to you. James Hardie Contractor Alliance™ Program — **our business is building yours.** 

Start putting the program to work for you at HardieAlliance.com



# SO COST EFFECTIVE it practically PAYS FOR ITSELF




Upgrading a garage door is one of the most cost effective renovations your clients can make. In fact, according to the Cost vs. Value Report, replacing a basic garage door with an upgraded one from Overhead Door returned over 90% on original cost. Now, that's a return on investment you can take to the bank.

The Genuine. The Original.



www.OverheadDoor.com


\* Based on National Association of Realtors members included in Cost vs. Value Study for midrange projects rather than actual sales data. Complete data from the Remodeling 2016 Cost vs. Value report can be downloaded at www.costvsvalue.com.



Visit www.provia.com to find out how you can experience The Professional Way.



Doors | Windows | Siding | Stone



Visit www.provia.com to find out how you can experience The Professional Way.









# Introducing Revive pocket replacement windows

Why choose Windsor's replacement windows? We've got a pocket full of reasons.



### **Trusted Name**

Outstanding quality customers expect from Windsor – in an all-new line of pocket replacement windows.



### **Energy Efficiency**

Replacement windows improve thermal performance, keeping customers comfortable while reducing heating and cooling bills.



### **Easy Installation**

Quick and simple replacement process — often it requires no trim removal — means windows typically install in about an hour.



### Precise Fit

Built to exact specifications for a perfect fit, every time.



### **Endless Options**

Three construction materials with multiple glass, grille, hardware, color and finish combinations sure to fit any style.



### **Fast Delivery**

Place your order and receive the windows in three to four weeks.



Visit www.windsorrevive.com to discover even more reasons to choose Revive.